

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of: ) Examiner: Lamson Nguyen  
MINEO KANEKO ET AL. :  
Application No.: 09/742,431 ) Group Art Unit:  
Filed: December 22, 2000 ) U.S. Patent No.: 6,964,467 B2  
For: LIQUID EJECTING RECORDING HEAD ) Issued: November 15, 2005  
AND LIQUID EJECTING RECORDING ) Confirmation No.: 8878  
APPARATUS ) November 14, 2006

Commissioner for Patents  
P.O. Box 1450  
Alexandria, Virginia 22313-1450

**ATTENTION: CERTIFICATES OF CORRECTION BRANCH****REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

The Commissioner is hereby authorized to charge Deposit Account No. 06-1205 for \$100.00 to cover the statutory fee for such Certificate of Correction. Please charge any required additional fee or credit any overpayment to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Jack S. Cubert/  
Jack S. Cubert  
Attorney for Patentees  
Registration No. 24,245

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
Facsimile: (212) 218-2200

JSC/lip  
DC\_MAIN 232338v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,964,467 B2

DATED : November 15, 2005

INVENTOR(S) : MINEO KANEKO ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At (56) References Cited

FOREIGN PATENT DOCUMENTS

after "5,367,325 A	11/1994	Abe et al.....347/43"
insert --5,621,524	04/1997	Mitani
5,697,144	12/1997	Mitani et al.--.

At (56) References Cited

FOREIGN PATENT DOCUMENTS

before "EP 0244643	11/1987"
insert --JP 8-207291	08/1996
JP 8-207320	08/1996
JP 10-140487	05/1998
JP 11-320926	11/1999--.

COLUMN 5

Line 9, "eject" should read --ejects--.

Line 50, "while" should be deleted.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,964,467 B2

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

DC\_MAIN 232338v1

DWP/klm



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,964,467 B2

DATED : November 15, 2005

INVENTOR(S) : MINEO KANEKO ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 7**

Line 17, "make make" should --make--.

Line 55, "(1.2x6+0.2x5)." should read --(=1.2x6+0.2x5).--

**COLUMN 8**

Line 5, " $t_1 \approx t_2 \approx 40$ " should read -- $t_1 = t_2 \approx 40$ --.

Line 6,  $\mu$  (1/600 inch.)" should read -- $\mu\text{m}$  (1/600 inch).--.

**COLUMN 9**

Line 44, "appears" should read --appear--.

**COLUMN 10**

Line 16, "will be not" should read --will not--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,964,467 B2

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

DC\_MAIN 232338v1

DWP/klm



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,964,467 B2

DATED : November 15, 2005

INVENTOR(S) : MINEO KANEKO ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 11**

Line 7, "will be not" should read --will not--.

Line 26, "will be not" should read --will not--.

Line 61 "may a" should read --may be a--.

**COLUMN 13**

Line 10, "provided" should read --provided to--.

Line 49, "outlet in" should read --outlets in--.

**COLUMN 14**

Line 40, "claim 10" should read --claim 11--.

**COLUMN 16**

Line 11, "arc" should read --are--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,964,467 B2

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

DC\_MAIN 232338v1

DWP/klm



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,964,467 B2

DATED : November 15, 2005

INVENTOR(S) : MINEO KANEKO ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 17**

Line 48, "liquid" should read --liquid supply--.

**COLUMN 18**

Line 25, "direction" should read --direction; and--.

Line 33, "respect" should read --respect to the--.

Line 39, "first" should read --said first--.

DC\_MAIN 232338v1

MAILING ADDRESS OF SENDER:

PATENT NO. 6,964,467 B2

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

DC\_MAIN 232338v1

DWP/klm

